

Ship Name:	ALKYON	Ship Type:	Chemical Tankship
IMO Number:	8025472	Flag:	Bahamas
Date Detained:	03/04/2002	Class Society:	Lloyd's Register of Shipping
Port:	Houston, Texas	Company(s):	<u>Owners, Operators or Managers</u> Ionia Management S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	2545 - Reports/analysis of non-conformities, etc.	Master and/or crew were not familiar with essential shipboard procedures relating to the prevention of pollution by oil in their failure to report the daily discharge of oil from the stern tubes of approximately 250-300 liters of oil.
	1799 - Other (MARPOL Annex I)	Vessel did not provide immediate notification to the nearest coastal state of stern tube seal oil pollution.
	1780 - Pollution report - annex I	The vessel failed to report a pollution incident without delay to the fullest extent possible in accordance with the provisions of Protocol I to the present convention.
	1499 - Other (Prop. & Aux. Machinery)	Stern tube is leaking oil at a rate of 250-300 liters per day due to improper seal.

Ship Name:	AMBROSIO	Ship Type:	Oil Tankship
IMO Number:	8114998	Flag:	Venezuela
Date Detained:	03/06/2002	Class Society:	American Bureau of Shipping
Port:	St. Croix, USVI	Company(s):	<u>Owners, Operators or Managers</u> PDV Marina

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0711 - Inert gas system	Deck water seal holed and inert gas system has multiple soft patches.

Ship Name:	ASAHI	Ship Type:	Refrigerated Cargo Carrier
IMO Number:	9004657	Flag:	Panama
Date Detained:	03/05/2002	Class Society:	Nippon Kaiji Kyokai
Port:	Dutch Harbor, Alaska	Company(s):	<u>Owners, Operators or Managers</u> Forest Commercial S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0220 - Certificates of competency	Master, Chief Officer and 1st Engineer did not have valid Panamanian licenses
	0950 - Electric equipment in	Emergency generator will not auto-start and assume emergency load.
	0710 - Fire prevention	Bulkhead penetrations in galley leading to officers and crew messrooms do not meet the structural fire protection requirements for the space (A/0). This includes the 2 fire screen doors leading to the mess rooms do not close or latch shut.
	1730 - Oily-water separating equipment	Discovered unsatisfactory branch line leading directly overboard which contained oil residue inside valve indicating the bypassing of the OWS directly overboard.

Ship Name:	BONAIRE	Ship Type:	Tankship (Not Specified)
IMO Number:	8111831	Flag:	Cyprus
Date Detained:	03/17/2002	Class Society:	Germanischer Lloyd
Port:	Guayama, Puerto Rico	Company(s):	<u>Owners, Operators or Managers</u> Kompass Reederie, GMBH

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0936 - Steering gear	Inoperable steering pump

Ship Name:	DOCE ISLAND	Ship Type:	Bulk Carrier
IMO Number:	9161742	Flag:	Liberia
Date Detained:	03/15/2002	Class Society:	American Bureau of Shipping
Port:	Long Beach, California	Company(s):	<u>Owners, Operators or Managers</u> Navegacao Vale Do Rio Doce S.A.

Docenave

Seamar Shipping Corp

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0945 - Emergency lighting, etc	Emergency generator unable to carry ship's electrical load in any mode.

Ship Name: **H HASAN YARDIM**
IMO Number: **8307832**
Date Detained: **03/29/2002**
Port: **Jacksonville, Florida**

Ship Type: **Refrigerated Cargo Carrier**
Flag: **Turkey**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Eser Denizcilik Ve Ticaret
Kaptanoglu Shipping Ltd.

Deficiencies: Code - Category
0110 - Cargo ship safety

Description
Certificate in doubt due to conflicting copies of document.

Ship Name: **JAMES SURVEYOR**
IMO Number: **7390961**
Date Detained: **03/06/2002**
Port: **Jacksonville, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Belize**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Moby 1 Inc.

Deficiencies: Code - Category
0230 - Number/composition (manning)
0635 - Launch arrangt. for rescue Boats

Description
Crew did not meet minimum safe manning requirements.
Rescue boat davit/crane inoperable.

Ship Name: **LINA**
IMO Number: **7622766**
Date Detained: **03/28/2002**
Port: **New Orleans, Louisiana**

Ship Type: **Bulk Carrier**
Flag: **Saint Vincent and the Grenadines**
Class Society: **Lloyd's Register of Shipping**
Company(s): Owners, Operators or Managers
Harehill Business Inc
Bernuth Agencies, Inc.

Deficiencies: Code - Category
2020 - Fire drills
0720 - Fire fighting equipment
2525 - Masters responsibility and authority

Description
Crew unable to demonstrate proficiency in fire drill.
Fire main piping holed and wasted in several areas on the cargo deck.
An external audit of the vessel's Safety Management System is required to address the Master's and Chief Officer's lack of familiarity with the vessel's Safety Management System.

Ship Name:	NORSUL RIO	Ship Type:	Bulk Carrier
IMO Number:	8128664	Flag:	Brazil
Date Detained:	03/26/2002	Class Society:	Det Norske Veritas
Port:	Philadelphia, Pennsylvania	Company(s):	<u>Owners, Operators or Managers</u> Companhia De Navegacao Norsul

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	2555 - Documentation	Objective evidence indicates reporting procedures not properly followed. No reports made in 7 months. Reports made only after CG inspection revealed discrepancies.
	0610 - Lifeboats	Class must attest to proper repair of stbd rescue boat and provide class report to USCG prior to departure.
	2565 - Certification, verification and control	Class must attest to the status of past due conditions of class and provide written report to USCG within 30 days.

Ship Name:	OSTROV BERINGA	Ship Type:	Refrigerated Cargo Carrier
IMO Number:	8517815	Flag:	Panama
Date Detained:	03/22/2002	Class Society:	Nippon Kaiji Kyokai
Port:	Dutch Harbor, Alaska	Company(s):	<u>Owners, Operators or Managers</u> Magna Services S.A. Laskaridis Shipping Co. Ltd

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0710 - Fire prevention	Provide doors for the AO bulkhead penetrations in galley leading to the officer and crew mess rooms, and /or effect temporary repairs to the satisfaction of class
	1730 - Oily-water separating equipment	Prove proper operation of oily water separator to the satisfaction of class.

Ship Name:	PANAM PERIA	Ship Type:	Chemical Tankship
IMO Number:	9084671	Flag:	Singapore
Date Detained:	03/12/2002	Class Society:	Nippon Kaiji Kyokai
Port:	Galveston, Texas	Company(s):	<u>Owners, Operators or Managers</u> Maruta Industries Co. LTD. Shenlong Maritime Co.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0610 - Lifeboats	Port lifeboat water spray system and forward releasing mechanism inoperative. Also missing grapppling lines and port-holes have multiple cracks.

Ship Name:	PERLA	Ship Type:	General Dry Cargo Ship
IMO Number:	7640471	Flag:	Panama
Date Detained:	03/18/2002	Class Society:	American Bureau of Shipping
Port:	New Orleans, Louisiana	Company(s):	<u>Owners, Operators or Managers</u> Marlow Trading
Deficiencies:	<u>Code - Category</u> 0135 - Minimum safe manning certificate 2020 - Fire drills 0735 - Personal equipment - fire fighting	<u>Description</u> Vessel not manned in accordance with minimum safe manning certificate. Vessel crew unable to demonstrate proficiency in a fire drill. Self-contained breathing apparatus bottles are not sufficiently charged.	

Ship Name:	STELAPRIMA	Ship Type:	General Dry Cargo Ship
IMO Number:	8912326	Flag:	Netherlands Antilles
Date Detained:	03/21/2002	Class Society:	Lloyd's Register of Shipping
Port:	Galveston, Texas	Company(s):	<u>Owners, Operators or Managers</u> Kahn Scheepvaart B.V.
Deficiencies:	<u>Code - Category</u> 2020 - Fire drills 0735 - Personal equipment - fire fighting	<u>Description</u> Crew unable to demonstrate proficiency in a fire drill Vessel missing 2 complete firemans outfits required by SOLAS.	